

Style NO		Art no	Art Work	W (In)	H (in)	Price (LKR) Each Pcs	PER ROW
HOT WEATHER CUT SHIRT	Heat Transfer	16-1	 PLATATAC HOT WEATHER CLIMATE CUTS SHIRT MACHINE WASH COLD. DO NOT IRON. RINSE THOROUGHLY.DO NOT BLEACH. TUMBLE DRY LOW. DO NOT DRY CLEAN. DO NOT USE FABRIC SOFTENER. ML	6CM	5CM	Rs.45/-	7
HOT WEATHER Tac DAX	Heat Transfer	16-2	 PLATATAC HOT WEATHER CLIMATE TAC DAX MACHINE WASH COLD. DO NOT IRON. RINSE THOROUGHLY.DO NOT BLEACH. TUMBLE DRY LOW. DO NOT DRY CLEAN. DO NOT USE FABRIC SOFTENER. 36R	6CM	5CM	Rs.45/-	7